Barn 1 Annexe

Barn 2 Annexe

new wall with timber cladded exterior within existing bay

existing roof tiles removed, roof repaired and matching tiles added

original opening reformed to include window within fake door panel

stained hardwood cladding to consented doors within barn conversions. timber framed window set within

frosted glass to WCs

existing columns restored , retained painted black

black aluminium window frames with sliding sections

North west elevation
Scale 1:100